Date: $3-7-25$ Time: $8:30 \text{ Am}$ Inspector(s)	Position: JIM RETCHUM	
Site Conditions: MostLy Sky: CLOUDY Ground Moisture: Light Damp Temp	erature: 59°F Precipitation: NONE	
Berms – Landfill Unit 2: Conditions Limiting Visibility: □ Snow Cover	□ Other	
Vegetation	□ None	
Observations: □ Erosion / Gullies □ Cracking / Sloughing □ Seeps / Damp Areas □ Signs of Creep □ Failed/eroded vegetation >100sq ft. Describe findings. Identify locations on attached map. Attached	□ Sudden drop in impoundment level □ Actual or potential structural weakness □ Improper operation of overtopping control □ Visible release ➤ No observed problems ch additional pages if necessary.	



Berms - Dallman Ash Pond

	Dumian Aon I Ona		
Condit	ions Limiting Visibility:		
	Snow Cover		Other
×	Vegetation NW CRNR		None
Obser	vations:		
	Erosion / Gullies		Sudden drop in impoundment level
	Cracking / Sloughing		Actual or potential structural weakness
	Seeps / Damp Areas		Improper operation of overtopping control
	Signs of Creep		Visible release
	Failed/eroded vegetation >100sq ft.	X	No observed problems
Describe findings. Identify locations on attached map. Attach additional pages if necessary.			
-			



Berms -	Lakeside	Ash Pond
---------	----------	----------

	Lancoldo Morri Oria		
Condit	ions Limiting Visibility:		
	Snow Cover		Other
	Vegetation	X,	None
Obser	vations:		
	Erosion / Gullies		Sudden drop in impoundment level
	Cracking / Sloughing		Actual or potential structural weakness
×	Seeps / Damp Areas		Improper operation of overtopping control
	Signs of Creep		Visible release
	Failed/eroded vegetation >100sq ft.		No observed problems
Describe findings. Identify locations on attached map. Attach additional pages if necessary.			
			TRACE SEEPAGE FROM
			NE LSAP INTO DITCH
		-	AND DRAINING INTO
			CLARIFICATION POND.



Berms – Lime Softening Ponds

Conditions Limiting Visibility: □ Snow Cover □ Vegetation	□ Other None		
Observations: □ Erosion / Gullies □ Cracking / Sloughing □ Seeps / Damp Areas □ Signs of Creep □ Failed/eroded vegetation >100sq ft.	 □ Sudden drop in impoundment level □ Actual or potential structural weakness □ Improper operation of overtopping control □ Visible release ☒ No observed problems 		
Describe findings. Identify locations on attached map. Attach additional pages if necessary.			



Areas of Previous Repair(s): Location:		
Effecti	veness of Repair:	
	Problem completely remedied	
	Problem partially remedied (explain below):	
	Problem not remedied (explain below):	
	Progression of trouble into new area (explain):	
	of Davidson Davidson	
	of Previous Repair(s):	
Locati		
Descri	ption of Repair:	
······································		
Effecti	veness of Repair:	
	Problem completely remedied	
	Problem partially remedied (explain below):	
لــا	Problem not remedied (explain below).	
	Progression of trouble into new area (explain):	

Additional Notes:	

	·

	······································