### City Water, Light and Power Coal Combustion Residuals Units 40 CFR 257 and 35 IAC 845

**Weekly Inspection Form** 

Date: 10.22.25 Time: 1:00 PM Inspector(s) / Position: VIM METCHUM			
Site Conditions:  Sky: SunnY Ground Moisture: DRY Temperature: 57 F Precipitation: NONE			
Berms – Landfill Unit 2:  Conditions Limiting Visibility:  □ Snow Cover □ Vegetation	□ Other		
Observations:  □ Erosion / Gullies □ Cracking / Sloughing □ Seeps / Damp Areas □ Signs of Creep □ Failed/eroded vegetation >100sq ft.	<ul> <li>□ Sudden drop in impoundment level</li> <li>□ Actual or potential structural weakness</li> <li>□ Improper operation of overtopping control</li> <li>□ Visible release</li> <li>▼ No observed problems</li> </ul>		
Describe findings. Identify locations on attached map. Attach additional pages if necessary.			



### Berms - Dallman Ash Pond

Condit	ions Limiting Visibility:		
	Snow Cover		Other
	Vegetation	X	None
Obser	vations:		
	Erosion / Gullies		Sudden drop in impoundment level
	Cracking / Sloughing		Actual or potential structural weakness
	Seeps / Damp Areas		Improper operation of overtopping control
	Signs of Creep		Visible release
	Failed/eroded vegetation >100sq ft.	X	No observed problems
Describe findings. Identify locations on attached map. Attach additional pages if necessary.			



Berms	<ul> <li>Lakeside Ash Pond</li> </ul>			
Conditions Limiting Visibility:				
	Snow Cover		Other	
	Vegetation	×	None	
Obser	vations:			
	Erosion / Gullies		Sudden drop in impoundment level	
	Cracking / Sloughing		Actual or potential structural weakness	
	Seeps / Damp Areas		Improper operation of overtopping control	
	Signs of Creep		Visible release	
	Failed/eroded vegetation >100sq ft.	×	No observed problems	
Describe findings. Identify locations on attached map. Attach additional pages if necessary.				



### Berms - Lime Softening Ponds

Condit	ions Limiting Visibility: Snow Cover Vegetation		Other
Observ	vations: Erosion / Gullies Cracking / Sloughing Seeps / Damp Areas Signs of Creep Failed/eroded vegetation >100sq ft.		Sudden drop in impoundment level Actual or potential structural weakness Improper operation of overtopping control Visible release No observed problems
Describe findings. Identify locations on attached map. Attach additional pages if necessary.			



Areas of Previous Repair(s):  Location:		
	veness of Density	
	veness of Repair:	
	Problem completely remedied	
	Problem partially remedied (explain below):	
	Problem not remedied (explain below):	
	Progression of trouble into new area (explain):	
Locati	of Previous Repair(s):	
Descri	ption of Repair:	
Effecti	veness of Repair:	
	Problem completely remedied	
	Problem partially remedied (explain below):	
	Problem not remedied (explain below):	
	Progression of trouble into new area (explain):	

Additional Notes:	