
Date	12-28-2022	Time		9:30 AM
Inspec	tor(s) / Position:	KETCHUN	1	
Site Conditions: FR 02 EN				
Sky: 5UNNY Ground Moisture: LTSNOW CVR Temperature: 38°F Precipitation: NONE				
Berms – Landfill Unit 2:				
Condit	ions Limiting Visibility:			
	Snow Cover		1	Other
×	Vegetation		l	None
Obser	vations:			
	Erosion / Gullies		1	Sudden drop in impoundment level
	Cracking / Sloughing		1	Actual or potential structural weakness
	Seeps / Damp Areas		1	Improper operation of overtopping control
	Signs of Creep		i i	Visible release
	Failed/eroded vegetation >100sq ft.	岚		No observed problems
Describe findings. Identify locations on attached map. Attach additional pages if necessary.				



Berm	s – Daliman Ash Pond		
Condi	tions Limiting Visibility:		
	Snow Cover		Other
X	Vegetation		None
Obser	vations:		
	Erosion / Gullies		Sudden drop in impoundment level
	Cracking / Sloughing		Actual or potential structural weakness
	Seeps / Damp Areas		Improper operation of overtopping control
	Signs of Creep		Visible release
	Failed/eroded vegetation >100sq ft.	×	No observed problems
Descr	ibe findings. Identify locations on attached	l map. Attach ad	ditional pages if necessary.



Berm	s – Lakeside Ash Pond		
Condi	tions Limiting Visibility:		
	Snow Cover		Other
×	Vegetation		None
Obser	vations:		
	Erosion / Gullies		Sudden drop in impoundment level
	Cracking / Sloughing		Actual or potential structural weakness
	Seeps / Damp Areas		Improper operation of overtopping control
	Signs of Creep		Visible release
	Failed/eroded vegetation >100sq ft.	×	No observed problems
Descr	ibe findings. Identify locations on attached i	map. Attach ad	ditional pages if necessary.



Berm	s – Lime Softening Ponds		
Condit	tions Limiting Visibility:		
	Snow Cover		Other
×	Vegetation		None
Obser	vations:		
	Erosion / Gullies		Sudden drop in impoundment level
	Cracking / Sloughing		Actual or potential structural weakness
	Seeps / Damp Areas		Improper operation of overtopping control
	Signs of Creep		Visible release
	Failed/eroded vegetation >100sq ft.	X	No observed problems
Describe findings. Identify locations on attached map. Attach additional pages if necessary.			



Areas of Previous Repair(s):		
Location: Description of Repair:		
Effect	iveness of Repair:	
	Problem completely remedied	
	Problem partially remedied (explain below):	
	Problem not remedied (explain below):	
	Progression of trouble into new area (explain):	
Areas	s of Previous Repair(s):	
	ion:	
	ription of Repair:	
D0001	The state of the pair.	
Effect	tiveness of Repair:	
	Problem partially remedied (explain below):	
	Problem not remedied (explain below):	
	Decree in the Charles in the Control of the Control	
	Progression of trouble into new area (explain):	

Additional Notes:	

