
Date: 4-16-25 Time: 7:45 AM Inspector(s) / Position: Jim KETCHUM				
Site Conditions:				
Sky: Sunny Ground Moisture: DRY Temperature: 41°F Precipitation: NONE				
Berms – Landfill Unit 2:				
Conditions Limiting Visibility:				
□ Snow Cover □ Other				
∀ Vegetation  □ None				
Observations:				
□ Erosion / Gullies □ Sudden drop in impoundment level				
□ Cracking / Sloughing □ Actual or potential structural weakness				
□ Seeps / Damp Areas □ Improper operation of overtopping control				
□ Signs of Creep □ Visible release				
□ Failed/eroded vegetation >100sq ft. No observed problems				
Describe findings. Identify locations on attached map. Attach additional pages if necessary.				



### Berms - Dallman Ash Pond

Condit	ions Limiting Visibility:			
	Snow Cover		Other	
×	Vegetation		None	
Obser	vations:			
	Erosion / Gullies		Sudden drop in impoundment level	
	Cracking / Sloughing		Actual or potential structural weakness	
	Seeps / Damp Areas		Improper operation of overtopping control	
	Signs of Creep		Visible release	
	Failed/eroded vegetation >100sq ft.	×	No observed problems	
Describe findings. Identify locations on attached map. Attach additional pages if necessary.				
***************************************				



### Berms - Lakeside Ash Pond

	241001407101110114		
Condit	tions Limiting Visibility:		
	Snow Cover		Other
	Vegetation	X	None
Obser	vations:		
	Erosion / Gullies		Sudden drop in impoundment level
	Cracking / Sloughing		Actual or potential structural weakness
×	Seeps / Damp Areas		Improper operation of overtopping control
	Signs of Creep		Visible release
	Failed/eroded vegetation >100sq ft.		No observed problems
Descri	be findings. Identify locations on attached map. Attach	n add	ditional pages if necessary.
			SEEPAGE FROM NE LSAP
•			INTO DITCH AND DRAINING



### Berms - Lime Softening Ponds

Condit	tions Limiting Visibility: Snow Cover Vegetation	□ <b>⋊</b>	Other None			
Obser	vations:  Erosion / Gullies  Cracking / Sloughing  Seeps / Damp Areas  Signs of Creep  Failed/eroded vegetation >100sq ft.		Sudden drop in impoundment level Actual or potential structural weakness Improper operation of overtopping control Visible release No observed problems			
Describe findings. Identify locations on attached map. Attach additional pages if necessary.						



Areas of Previous Repair(s):					
Location:					
	Description of Repair:				
***************************************					
Effecti	veness of Repair:				
	Problem completely remedied				
	Problem partially remedied (explain below):				
	Problem not remedied (explain below):				
<u></u>	Troblem not remedied (explain below).				
	Progression of trouble into new area (explain):				
Areas	of Previous Repair(s):				
	on:				
	ption of Repair:				
Descri	phon of repair.				
Effecti	veness of Repair:				
	Problem completely remedied				
	Problem partially remedied (explain below):				
	Problem not remedied (explain below):				
	Dragraggian of trouble into pays area (cynlain):				
	Progression of trouble into new area (explain):				

Additional Notes:			
	····		
	<del></del>		
	***************************************		
	***************************************		
	<u></u>		
	<del></del>		
	***************************************		
	<u></u>		