
Date: 4/30/25 Time: //:30 Inspector(s) /	Position: Schy Willmore
Site Conditions:	light vain
Sky: Guvcust Ground Moisture: Wet Tempe	rature: 58 Precipitation: at start
Berms – Landfill Unit 2:	
Conditions Limiting Visibility:	
□ Snow Cover	□ Other
□ Vegetation	None
Observations:	
□ Erosion / Gullies	□ Sudden drop in impoundment level
□ Cracking / Sloughing	☐ Actual or potential structural weakness
□ Seeps / Damp Areas	☐ Improper operation of overtopping control
□ Signs of Creep	□ Visible release
☐ Failed/eroded vegetation >100sq ft.	No observed problems
	2
Describe findings. Identify locations on attached map. Attac	h additional pages if necessary.



#### Berms - Dallman Ash Pond

Condit	tions Limiting Visibility:		
	Snow Cover		Other
	Vegetation	70	None
Obser	vations:	•	
	Erosion / Gullies		Sudden drop in impoundment level
	Cracking / Sloughing		Actual or potential structural weakness
	Seeps / Damp Areas		Improper operation of overtopping control
	Signs of Creep		Visible release
	Failed/eroded vegetation >100sq ft.	X	No observed problems
Descri	be findings. Identify locations on attached map. Attach	ado	ditional pages if necessary.
**************************************			
***************************************			



Berms - Lakeside As	sh	Po	nd
---------------------	----	----	----

3011110		
Condit	ions Limiting Visibility:	
	Snow Cover	□ Other
	Vegetation	None
Obser	vations:	
	Erosion / Gullies	☐ Sudden drop in impoundment level
	Cracking / Sloughing	□ Actual or potential structural weakness
	Seeps / Damp Areas	☐ Improper operation of overtopping control
	Signs of Creep	□ Visible release
	Failed/eroded vegetation >100sq ft.	No observed problems
Descri	be findings. Identify locations on attached map. Attac NO Seeps observed, thou could have made obse	



#### **Berms – Lime Softening Ponds**

Condi	tions Limiting Visibility: Snow Cover Vegetation	□ Other None
Obser	vations: Erosion / Gullies Cracking / Sloughing Seeps / Damp Areas Signs of Creep Failed/eroded vegetation >100sq ft.	<ul> <li>□ Sudden drop in impoundment level</li> <li>□ Actual or potential structural weakness</li> <li>□ Improper operation of overtopping control</li> <li>□ Visible release</li> <li>□ No observed problems</li> </ul>
Descri	be findings. Identify locations on attached map. Atta	ach additional pages if necessary.



Areas	Areas of Previous Repair(s):	
Location:		
	iption of Repair:	
***************************************		
Effect	iveness of Repair:	
	Problem completely remedied	
	Problem partially remedied (explain below):	
	Problem not remedied (explain below):	
-	Troblem net remedied (explain selett).	
	Progression of trouble into new area (explain):	
Arose	of Previous Repair(s):	
	on:	
Descr	iption of Repair:	
Effect	iveness of Repair:	
	Problem completely remedied	
	Problem partially remedied (explain below):	
	Problem not remedied (explain below):	
	Progression of trouble into new area (explain):	

Additional Notes: