
Date:	5/21/25 Time: 12:30 Inspe	ector(s) / Position: Schy Willmore		
	Site Conditions:			
Sky:	Cloudy Ground Moisture: Wet	_Temperature: 60 Precipitation: 10012		
Berms	Berms – Landfill Unit 2:			
Condit	tions Limiting Visibility:			
	Snow Cover	□ Other		
	Vegetation	None		
Obser	vations:	/		
	Erosion / Gullies	☐ Sudden drop in impoundment level		
	Cracking / Sloughing	☐ Actual or potential structural weakness		
	Seeps / Damp Areas	☐ Improper operation of overtopping control		
	Signs of Creep	☐ Visible release		
	Failed/eroded vegetation >100sq ft.	No observed problems		
Describe findings. Identify locations on attached map. Attach additional pages if necessary.				



#### Berms – Dallman Ash Pond

Delilli	5 - Dailinan Ash Fond		
Condit	tions Limiting Visibility:		
	Snow Cover		Other
	Vegetation	×	None
Obser	vations:	/	
	Erosion / Gullies		Sudden drop in impoundment level
	Cracking / Sloughing		Actual or potential structural weakness
	Seeps / Damp Areas		Improper operation of overtopping control
	Signs of Creep		Visible release
	Failed/eroded vegetation >100sq ft.	Æ	No observed problems
Descri	be findings. Identify locations on attached	map. Attach add	ditional pages if necessary.
		***************************************	



Berms –	Lakeside	Ash Pond
---------	----------	----------

2611113	- Lakeside Asii Fulid		
Condit	ions Limiting Visibility:		
	Snow Cover		Other
	Vegetation	$\gg$	None
Obser	vations:	/	
	Erosion / Gullies		Sudden drop in impoundment level
	Cracking / Sloughing		Actual or potential structural weakness
	Seeps / Damp Areas		Improper operation of overtopping control
	Signs of Creep		Visible release
	Failed/eroded vegetation >100sq ft.	M	No observed problems
Describe findings. Identify locations on attached map. Attach additional pages if necessary.			
	<del>-</del>		



#### Berms - Lime Softening Ponds

Condit	ions Limiting Visibility: Snow Cover Vegetation		Other	
Observed Control of the Control of t	vations: Erosion / Gullies Cracking / Sloughing Seeps / Damp Areas Signs of Creep Failed/eroded vegetation >100sq ft.		Sudden drop in impoundment level Actual or potential structural weakness Improper operation of overtopping control Visible release No observed problems	
Describe findings. Identify locations on attached map. Attach additional pages if necessary.				



Areas	Areas of Previous Repair(s):		
Location:			
Descr	Description of Repair:		
***************************************			
Effect	iveness of Repair:		
	Problem completely remedied		
	Problem partially remedied (explain below):		
	Problem not remedied (explain below):		
	Progression of trouble into new area (explain):		
<b>A</b>	of Burning Barrelofa's		
	s of Previous Repair(s):		
Locati	on:		
Descr	iption of Repair:		
************			
***************************************			
Effect	iveness of Repair:		
	Problem completely remedied		
	•		
	Problem not remedied (explain below):		
لسا	robiem not remedied (explain below).		
	Progression of trouble into new area (explain):		

Additional Notes:	
	, , , , , , , , , , , , , , , , , , ,
	***************************************
	<b></b>
	***************************************
***************************************	
***************************************	***************************************