

/ / Weekly inspection form				
Date: 9/24/25 Time: 10:45 Inspector(s) / 1	Posi	tion: Schy William		
Site Conditions:		,		
Sky: Overlast Ground Moisture: Champ Temper	atur	re: 70 Precipitation: None		
,				
Berms – Landfill Unit 2:				
Conditions Limiting Visibility:				
□ Snow Cover		Other		
Vegetation		None		
Observations:				
□ Erosion / Gullies		Sudden drop in impoundment level		
☐ Cracking / Sloughing		Actual or potential structural weakness		
□ Seeps / Damp Areas		Improper operation of overtopping control		
□ Signs of Creep		Visible release		
☐ Failed/eroded vegetation >100sq ft.	X	No observed problems		
Describe findings. Identify locations on attached map. Attach additional pages if necessary.				



Berms - Dallman Ash Pond Conditions Limiting Visibility: □ Snow Cover □ Other ∨egetation □ None Observations: □ Erosion / Gullies ☐ Sudden drop in impoundment level □ Cracking / Sloughing ☐ Actual or potential structural weakness □ Seeps / Damp Areas ☐ Improper operation of overtopping control □ Signs of Creep □ Visible release ☐ Failed/eroded vegetation >100sq ft. No observed problems Describe findings. Identify locations on attached map. Attach additional pages if necessary.



Berms - Lakeside Ash Pond

	Eurosido Asir i Orid		
Conditio	ons Limiting Visibility:		
	Snow Cover		Other
X	Vegetation		None
Observa	ations:		
	Erosion / Gullies		Sudden drop in impoundment level
	Cracking / Sloughing		Actual or potential structural weakness
	Seeps / Damp Areas		Improper operation of overtopping control
	Signs of Creep		Visible release
□ F	Failed/eroded vegetation >100sq ft.	X	No observed problems
Describe findings. Identify locations on attached map. Attach additional pages if necessary.			



Berms – Lime Softening Ponds

Delilli	s – Linie Soitening Ponds				
Condit	ions Limiting Visibility: Snow Cover Vegetation		OtherNone		
Obser	vations: Erosion / Gullies Cracking / Sloughing Seeps / Damp Areas Signs of Creep Failed/eroded vegetation >100sq ft.	D D D D	Sudden drop in impoundment level Actual or potential structural weakness Improper operation of overtopping control Visible release No observed problems		
Describe findings. Identify locations on attached map. Attach additional pages if necessary.					
	· · · · · · · · · · · · · · · · · · ·				



Areas of Previous Repair(s):			
Locati	on:		
	ption of Repair:		
Effecti	veness of Repair:		
	Problem completely remedied		
	Problem partially remedied (explain below):		
	Problem not remedied (explain below):		
	Progression of trouble into new area (explain):		
_			
	of Previous Repair(s):		
Locati	on:		
	ption of Repair:		

Effecti	veness of Repair:		
	Problem completely remedied		
	Problem not remedied (explain below):		
اسا	Troblem not remedied (explain below).		
	Progression of trouble into new area (explain):		

Additional Notes:	
	_
	_