Date: 10-1-25 Time: 8:30 km Inspector(s) / I	Posi	tion: JIM KETCHUM	
Site Conditions:			
Sky: Sunny Ground Moisture: DRY Temper	ratur	re: 63°F Precipitation: NONE	
Berms – Landfill Unit 2: Conditions Limiting Visibility:			
□ Snow Cover		Other	
▼ Vegetation		None	
Observations:			
☐ Erosion / Gullies		Sudden drop in impoundment level	
□ Cracking / Sloughing		Actual or potential structural weakness	
□ Seeps / Damp Areas		Improper operation of overtopping control	
☐ Signs of Creep		Visible release	
☐ Failed/eroded vegetation >100sq ft.	X	No observed problems	
Describe findings. Identify locations on attached map. Attach additional pages if necessary.			



Berms - Dallman Ash Pond

Condit	ions Limiting Visibility:		
	Snow Cover		Other
X	Vegetation		None
Obser	vations:		
	Erosion / Gullies		Sudden drop in impoundment level
	Cracking / Sloughing		Actual or potential structural weakness
	Seeps / Damp Areas		Improper operation of overtopping control
	Signs of Creep		Visible release
	Failed/eroded vegetation >100sq ft.	X	No observed problems
Describe findings. Identify locations on attached map. Attach additional pages if necessary.			



berms	- Lakeside Ash Pond		
Condit	ions Limiting Visibility:		
	Snow Cover		Other
X	Vegetation		None
Obser	vations:		
	Erosion / Gullies		Sudden drop in impoundment level
	Cracking / Sloughing		Actual or potential structural weakness
	Seeps / Damp Areas		Improper operation of overtopping control
	Signs of Creep		Visible release
	Failed/eroded vegetation >100sq ft.	X	No observed problems
Docori	be findings. Identify locations on attached map. Attacl	a add	litional pages if pagesany
Descri	be findings, identity locations on attached map. Attach	i aud	illional pages il necessary.



Berms - Lime Softening Ponds

Condit	tions Limiting Visibility: Snow Cover Vegetation		OtherNone
Obser	vations: Erosion / Gullies Cracking / Sloughing Seeps / Damp Areas Signs of Creep Failed/eroded vegetation >100sq ft.		Sudden drop in impoundment level Actual or potential structural weakness Improper operation of overtopping control Visible release No observed problems
Descri	be findings. Identify locations on attached map. Attac	h add	ditional pages if necessary.



Areas of Previous Repair(s):				
Location:				
Descri	iption of Repair:			
	vances of Donaire			
	veness of Repair:			
	Problem completely remedied			
	Problem partially remedied (explain below):			
	Problem not remedied (explain below):			
	Progression of trouble into new area (explain):			
	;			
Areas Locati	of Previous Repair(s):			
	iption of Repair:			
Effecti	veness of Repair:			
	Problem completely remedied			
	Problem partially remedied (explain below):			
	Problem not remedied (explain below):			
	Progression of trouble into new area (explain):			

Additional Notes:	
	A

	·

	•
	·······

	·····

	BC-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1