

**City Water, Light and Power
Coal Combustion Residuals Units
40 CFR 257 and 35 IAC 845
Weekly Inspection Form**

Date: 6-10-26 Time: 7:00 AM Inspector(s) / Position: Jim KETCHUM

Site Conditions:

Sky: SUNNY Ground Moisture: DAMP Temperature: 79°F Precipitation: NONE

Berms – Landfill Unit 2:

Conditions Limiting Visibility:

☐ Snow Cover

☒ Vegetation

☐ Other _____

☐ None

Observations:

☐ Erosion / Gullies

☐ Cracking / Sloughing

☐ Seeps / Damp Areas

☐ Signs of Creep

☐ Failed/eroded vegetation >100sq ft.

☐ Sudden drop in impoundment level

☐ Actual or potential structural weakness

☐ Improper operation of overtopping control

☐ Visible release

☒ No observed problems

Describe findings. Identify locations on attached map. Attach additional pages if necessary.



**City Water, Light and Power
Coal Combustion Residuals Units
40 CFR 257 and 35 IAC 845
Weekly Inspection Form**

Berms – Dallman Ash Pond

Conditions Limiting Visibility:

- ☐ Snow Cover
☒ Vegetation


- ☐ Other _____
☐ None

Observations:

- ☐ Erosion / Gullies
☐ Cracking / Sloughing
☐ Seeps / Damp Areas
☐ Signs of Creep
☐ Failed/eroded vegetation >100sq ft.

- ☐ Sudden drop in impoundment level
☐ Actual or potential structural weakness
☐ Improper operation of overtopping control
☐ Visible release
☒ No observed problems

Describe findings. Identify locations on attached map. Attach additional pages if necessary.



**City Water, Light and Power
Coal Combustion Residuals Units
40 CFR 257 and 35 IAC 845
Weekly Inspection Form**

Berms – Lakeside Ash Pond

Conditions Limiting Visibility:

☐ Snow Cover

☒ Vegetation

☐ Other _____

☐ None

Observations:

☐ Erosion / Gullies

☐ Cracking / Sloughing

☐ Seeps / Damp Areas

☐ Signs of Creep

☐ Failed/eroded vegetation >100sq ft.

☐ Sudden drop in impoundment level

☐ Actual or potential structural weakness

☐ Improper operation of overtopping control

☐ Visible release

☒ No observed problems

Describe findings. Identify locations on attached map. Attach additional pages if necessary.



**City Water, Light and Power
Coal Combustion Residuals Units
40 CFR 257 and 35 IAC 845
Weekly Inspection Form**

Berms – Lime Softening Ponds

Conditions Limiting Visibility:

- ☐ Snow Cover
- ☒ Vegetation

- ☐ Other _____
- ☐ None

Observations:

- ☐ Erosion / Gullies
- ☐ Cracking / Sloughing
- ☐ Seeps / Damp Areas
- ☐ Signs of Creep
- ☐ Failed/eroded vegetation >100sq ft.

- ☐ Sudden drop in impoundment level
- ☐ Actual or potential structural weakness
- ☐ Improper operation of overtopping control
- ☐ Visible release
- ☒ No observed problems

Describe findings. Identify locations on attached map. Attach additional pages if necessary.



**City Water, Light and Power
Coal Combustion Residuals Units
40 CFR 257 and 35 IAC 845
Weekly Inspection Form**

Areas of Previous Repair(s):

Location: _____

Description of Repair: _____

Effectiveness of Repair:

- ☐ Problem completely remedied
- ☐ Problem partially remedied (explain below):
- ☐ Problem not remedied (explain below):

- ☐ Progression of trouble into new area (explain):

Areas of Previous Repair(s):

Location: _____

Description of Repair: _____

Effectiveness of Repair:

- ☐ Problem completely remedied
- ☐ Problem partially remedied (explain below):
- ☐ Problem not remedied (explain below):

- ☐ Progression of trouble into new area (explain):

Additional Notes:

[illegible]